

## CENTRAL INTELLIGENCE AGENCY This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents to or receipt by an unauthorised person is prohibited INFORMATION REPORT by law. The reproduction of this form is prohibited. S-E-C-R-E-T 25X1 REPORT USSR (Ametic) COUNTRY MAR 25 1955 DATE DISTR. 25X1 **SUBJECT** Port of Murmansk NO. OF PAGES REQUIREMENT DATE OF INFO. 25X1 REFERENCES PLACE ACQUIRED 25X1 DATE ACQUIRED This is UNEVALUATED Information THE SOURCE EVALUATIONS IN THIS REPORT ARE DEFINITIVE. THE APPRAISAL OF CONTENT IS TENTATIVE. (FOR KEY SEE REVERSE) 1. 2. 25X1 double row of lights lying in a southwest to 3. northeast direction between Vayenga (N 69-05, E 33-27) and Rosta (N 69-03, 25X1 E 33-05). There were red and white lights in a row at least 10 small MTBs proceeding at high speed in the inlet. firing from a battery on 25X1 5. shore toward a vessel which was about four miles offshore. The shore battery was located on Voriv Point in the approximate position N 69-25, E 33-20. 25X1 The shots were fired in series; each series consisted or several masnes one after the other, followed by a pause. 25X1 a large naval vessel 6. 25X1 at the quay in Rosta. The vessel was at least 400 feet long; it had a break in the deckline between the command bridge and the forward stack. The vessel had two stacks, both of which had smoke cowls. There were two gun turrets on the foredeck and two on the afterdeck 25X1 The command bridge was en-25X1 closed by scaffolding and work was apparently being done on it (see sketch No. 1). S-E-C-R-E-T 25X1 STATE ARMY Washington Distribution Indicated By "X"; Field Distribution By "#".)

S-E-C-R-E-T

25X1 -2-7. There were a number of small vessels at the repair quay in Rosta. There were 25X1 also two identical vessels at anchor off the workshop Each vessel was about 350 feet long and had a break 25X1 in the deckline between the bridge and the forward stack. Each ship had two stacks equipped with smoke cowls, a tripod mast just forward of each stack, one gun turret on the foredeck, and a built-up structure and a number of guns on the 25X1 afterdeck. (see sketch No. 2). 25X1 8. There was a number of naval vessels on the west side of Roslyakova Bay (N 69-03, E 33-11). 25X1 9. On the south side of Vayenga Bay (N 69-05, E 33-26) there were many small naval vessels alongside the quay, and two large vessels at anchor in the bay. The two large vessels were very wide, and they were each about 350 to 400 feet long. One of the vessels had a break in the deckline between the stacks, and it had two stacks with smoke cowls, two tripod masts forward of each stack, a T-shaped 25X1 command bridge, and two gun turrets on both the foredeck and afterdeck. 25X1 On the forward mast there was a compact construction shaped like a truncated cone. 25X1 (see sketch No. 3). 25X1 10. The second vessel had a hull which was built up higher 25X1 (see sketch No. 4). The vessel had two stacks, and the after stack had a high-3.5 er smoke cowl than the forward one. There was a tripod mast located forward of each stack. The vessel also had a T-shaped command bridge, two gun turrets on both the foredeck and the afterdeck, and the same construction on the foremast There was a gangway on the port side at the break to the afterdeck25X1 (see sketch No. 4). Sketch No. 1: 25X1 Naval Vessel Sketch No. 2 25X1 Naval Vessel 25X1 S-E-C-R-E-T 25X1

S-E-C-R-E-T 25X1





<u>-E+C-R-E-T</u>

